

**PUBLIC RECORD UPDATE
March 2026**

FY 2025 Tribal Response Program

Site Name and Identification	Coordinates		Approximate Acreage	Owner at Time of Cleanup	Type of Site	Site Status and Information	Site Suitable For Reuse?
	Latitude	Longitude					
SITES WHERE RESPONSE ACTIONS WERE CONDUCTED IN 2025							
Air Warning Filter Center (Concern Group B)	59.51542	-139.70856	6	U.S. Forest Service	WW II	Approximately 18 CY of debris from wooden filter center, pumphouse, and two wooden bridges were removed. A geophysical survey was conducted to locate an underground storage tank (UST). An area was identified as a potential UST location. A site investigation was conducted around a former septic tank and around anomalies detected during the geophysical survey. Remaining debris recommended for removal at the site includes two structures, three concrete foundations, one UST (unknown location), and miscellaneous debris including piping and wire/cables.	No - Additional work required
Concern Group C: Pt. Carrew Garrison	59.55465	-139.84605	70	Regional Native Corporation	WW II	Assessment and design of culvert replacements occurred in 2025. Investigation of potential soil contamination in the vicinity of the Ankau Bridge occurred in 2025, to enable design of a replacement bridge. No major contamination was found in the bridge area. YTT reviewed information on petroleum contamination at former military sites in Concern Group C.	No - Additional work required
Army Dock Fuel Tanks (Concern Group D)	59.54528	-139.73417	2	Yak-Tat Kwaan, Inc. (Alaska Native Village Corporation)	WW II fuel storage	Approximately 2 CY of pipeline debris were removed from the Army Dock Fuel Tanks area. A site investigation is recommended to determine if the soil underneath the pipeline is contaminated with fuel from pipeline leaks.	No - Additional work required
St. Elias Auto Center	59.54490	-139.72776	0.43	YTT	gas station	YTT coordinated with ADEC on Phase I Site Investigation.	No - Additional work required
Minor Naval Air Facility (Seaplane Base, Concern Group G)	59.54417	-139.75667	6	State of Alaska	WW II facility	YTT conducted a field visit and prepared an investigation plan to assess contamination impacts of the former seaplane ramp.	No - Additional work required
Ocean Cape Radio Relay Station (Concern Group H)	59.54240	-139.85700	20	Yak-Tat Kwaan, Inc. (Alaska Native Village Corporation)	WW II and Cold War garrison	YTT reviewed information on dioxin contamination at the former Culture Camp area.	No - Additional work required
Elephant Shelter Road Dump Site (Concern Group P)	59.53300	-139.70700	0.25	State of Alaska	WW II dump site	YTT prepared a sampling plan to assess contamination impacts from the dump.	No - Additional work required
SITES WHERE RESPONSE ACTIONS ARE PLANNED IN 2026							
Concern Group C: Ankau Slough Bridge	59.55465	-139.84605	70	Regional Native Corporation	WW II	YTT plans to prepare a construction materials management plan to mitigate soil contamination in the vicinity of the Ankau Bridge, to enable construction of a replacement bridge.	No - Additional work required
Concern Group C: Pt. Carrew Garrison West Side	59.55465	-139.84605	70	Regional Native Corporation	WW II	YTT plans to remove wood and metal debris at two former dumps and one former powerhouse.	No - Additional work required

Minor Naval Air Facility (Seaplane Base, Concern Group G)	59.54417	-139.75667	6	State of Alaska	WW II facility	YTT plans to conduct a sampling investigation to identify if creosote contamination has been released from the former seaplane ramp.	No - Additional work required
Glacier Bear Road Dump Site / Elephant Shelter Road Dump Site (Concern Group P)	59.53300	-139.70700	0.25	State of Alaska	WW II dump site	YTT plans to conduct sampling to identify if contamination has been released from this dump.	No - Additional work required
SITES WHERE RESPONSE ACTIONS ARE PROPOSED IN 2026							
Concern Group E: Hospital area	59.522297	-139.680804	18	State of Alaska	WW II facility	YTT has proposed to prepare a plan to remove approximately 60 CY of metal debris and characterize the site contents for future removal. This activity is pending funding.	No - Additional work required